SR10 Quick Start Guide





Operation	Button	Duration	LED
Power-on	1) + 2)	On	Solid blue
Power-off		1 sec	Solid red
Bluetooth headset pairing	1	5 sec	Blue & red alternatively flashing
Mobile phone pairing		8 sec	Red flashing
Bluetooth headset reconnection	① or ②	-	Slow Blue Flashing
Mobile phone reconnection	1)		Slow Red Flashing



Please charge the battery fully before the first use.